




MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 23, Township 10 North, Range 2 West,


Monument Description & Remarks: 1/2" Rebar Fd. 0.4' Below Ground W/ Plastic Cap
Inscribed "Mundy LS 80014" In Centerline Gravel Road



COMPLETED By *Str. U. Tarkenton*

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E Bledsoe
 Indiana Registered Land Surveyor No. S0559



MONUMENT RECORD
State of Indiana - County of Monroe

Section: 23


Township: 10 North

Range: 2 West

Corner ID: Be BI U-13

Monument Description & Remarks: Found 1/2" Rebar in centerline of Bottom Road at NE corner of section. Rebar was bent over 6" at the top; straightened rebar and pounded it down 1" below road grade.

References on file in the County Surveyor's Office: Mike Mundy survey dated May, 1995.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 26th day of November, 1997.

Kevin P. Enright

Administered by: Surveyor Review Board

